ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W1713, W0982, W0978, W1393, W0796, W0980, W1000, W	NA, 4th Crs	Jakkur circle to Jakkur Govt school
Segment No.	**Total Length (m)**	
5/C-W1713/S050802	460.81	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	175.91	77.607036	13.078838	77.606758	13.077272	M0013	W0985
2	284.90	77.606928	13.076602	77.607386	13.079122	M0013	W1000

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads & Drains at JAKKUR in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	2000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads & Drains at JAKKUR in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-14-000007
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/336/2014-15	06/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
06/03/2015	05/03/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. CHANDRAPPA		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		CHANDRAKANTH
Date of Inspection	**Remarks**	
31/10/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1713, W0982, W0978, W1393,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	31/10/2016	30/11/2016	COMPLETED
SE	VASU K M	31/10/2016	30/11/2016	COMPLETED
EE	YARAPPA REDDY	31/10/2016	30/11/2016	COMPLETED
AEE	J N LOKESH	31/10/2016	30/11/2016	COMPLETED
AE	CHANDRAKANTH	31/10/2016	30/11/2016	COMPLETED
AE	CHANDRAKANTH	31/10/2016	30/11/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1713, W0982, W0978, W1393,